

# Pullex® Crocodile

## Mounting example of fixing plate C303 and C603.

The tables and sketches below show in which position the fixing plates should be mounted on the square part-off tool so that the frames should be able to manage a specific diameter range.



Drill and thread two holes M5x10 in the tool holder. Fix the fixing plate with 2 screws M5x10.

Frame	Fixing Plate	Gripping range (mm)	A (mm)
C30	C303	0-15 (0"-0,59")	43 (1,69")
		15-39 (0,59"-1,54")	58 (2,28")
C60	C603	30-45 (1,18"-1,77")	50 (1,97")
		45-60 (1,77"-2,36")	66 (2,60")

Visit us at <http://www.barpuller.com>

**MPC** MPC Automation Systems AB  
Box 5879, S-102 40 Stockholm, Sweden  
Phone:+46 8 6670950 Fax: +46 8 6670952